

Photo 1: M6 Propellant improperly stored outside by Explo



Photo 2: M6 Propellant scattered on the ground (after October 2012 explosion)



Photo 3: Result of explosion of magazine storing black powder and tractor trailers storing M6 Propellant in October 2012



Photo 4: Example of explosive storage magazine at Camp Minden



Photo 5: Trees growing on top of explosive storage magazine at Camp Minden



Photo 6: M6 propellant and Aluminum/TNT/Tritonal stored in explosive storage magazine at Camp Minden



Photo 6: Nitrocellulose stored in explosive storage magazine at Camp Minden



Photo 7: M6 Propellant spilled outside magazines exposed to elements



Photo 8: M119A2 155MM Propelling Charge provided to Explo by US Army for demilitarization; Origin of M6 Propellant



Photo 9: M6 propellant spilled on floor at S-Line (common throughout facility)



Photo 10: Result of explosion of magazine storing black powder and tractor trailers storing M6 Propellant in October 2012



Photo 11: Storage of M6 Propellant outside at Explo



Photo 12: M6 and Tritonal/Aluminum/TNT containers falling and spilling contents inside magazines